


# MASE



| Ref. | Pic. | H<br>(mm) | 200 | 200 | 300 | 1000 | 600 | 1000 |
|------|------|-----------|-----|-----|-----|------|-----|------|
|      |      |           | 350 | 800 | 800 | 1200 | 800 | 1200 |
|      |      |           | 150 | 300 | 500 | 600  | 800 | 800  |
|      |      |           | 250 | 400 | 600 |      |     |      |
| A    | M8   |           | 6   | 6   | 6   | 8    | 6   | 8    |
| B    |      |           | 4   | 4   | 4   | 6    | 4   | 6    |
| C    |      |           | 6   | 6   | 6   | 6    | 6   | 6    |
| D    |      |           | 1   | 1   | 1   | 1    | 1   | 1    |
| E    |      |           | 2   | 2   | 2   | 2    | 2   | 2    |

